

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

BOB PECK CHEVROLET  
800 North Glebe Road  
Arlington  
Virginia

HABS VA-1413

Photograph Nos. VA-1413-1 through VA-1413-2 were taken in April, and the remainder in early June 2006.

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, 2006

- |           |   |
|-----------|---|
| VA-1413-1 | General view looking generally southeast to northwest across the Glebe Road and Wilson Boulevard intersection and toward the dealership with its round showroom and "C-H-E-V-O-R-L-E-T" diamond-paneled marquee |
| VA-1413-2 | Perspective view of the showroom looking from the middle of the intersection of Glebe Road and Wilson Boulevard   |
| VA-1413-3 | View looking west to east toward the showroom   |
| VA-1413-4 | Perspective view to show rear (west) elevation (Note background skyline of ca. 2000 buildings & construction cranes across Glebe Road from the dealership)  |
| VA-1413-5 | View looking east across the parking lot alongside the facade of parts and service wing and toward the showroom generally   |
| VA-1413-6 | View looking northeast to the "parts and service entrance" and to the porte cochere connecting the showroom to the service area; note windows for what appears to be office space above                         |
| VA-1413-7 | Detail view of door to "parts and service entrance" to show door handle   |

BOB PECK CHEVROLET  
HABS VA-1413  
INDEX TO PHOTOGRAPHS

VA-1413-8	Interior view, parts and service area lobby
VA-1413-9	Interior view, service area with multiple bays